



Installing USB Device Drivers



The USB drivers can interface with Windows 98, 2000, or ME.

System files are needed when loading the USB drivers. These files may already be on your PC or you may be required to load them from the Microsoft CD that came with your PC.

- 1 Check that the USB cable is connected from the PC to the cable modem. If it has not been installed, refer to, "Installation For a Single User."
- 2 Insert the CD into the CD drive. The PC automatically recognizes the USB connection.



Installing USB Device Drivers



- 3 Click CD-ROM drive and Specify a location.
- 4 Click Browse.
- 5 Select your CD drive and USB drivers. Example: D:\USB DEVICE DRIVERS
- 6 Click Next to load the USB drivers.
- 7 Click Next to install the driver on the location displayed.
- 8 Insert your Microsoft Operating CD when prompted, if the operating system is not installed on the hard drive.
or
Click Next at the prompt, if the operating system is loaded on the hard drive.
- 9 Click Yes to restart your computer and finish setting up the new hardware.

